1/22





FIG. 1






FIG. 3

3/22




FIG. 4





FIG. 5

4/22



5/22




FIG. 7





FIG. 8

7/22






FIG.10A

FIG.10B




FIG.11




FIG.12

10/22




FIG.13




FIG.14

11/22




FIG.15




FIG. 16

Atty. Ref.: 9319S-000667

13/22




FIG.17




FIG.18

15/22




FIG.19




FIG.20





FIG.21

18/22



19/22

	С	М	Υ	С	М	Υ	С	М	
	w	М	w	w	w	Y	С	М	-22
	W	М	Y	w	w	Y	С	М	23
В —	С	М	Υ	С	M.	Y	С	М	25
	С	М	Υ	С	М	Y	С	М	T26
C —	w	w	W	С	w	W	С	М	27
	w	W	Y	W	w	W	С	w	
STRIPE REGION								1	A

FIG.23




FIG.24

20/22




FIG.25

21/22




FIG.26

22/22




FIG.27




FIG.28